

TOP SECRET 152308Z

OFC

1963 MAR 16 00 25Z

OUT 50806

LANYARD

REF: [ ] DRAWING 9228 E 43704 REVISED 28 JAN 63

1. UPON CHECKING SAMPLE NEGATIVES OF L FRAMES GIVEN [ ] 8  
MAR FIND DISCREPANCIES WITH REF DRAWING.

A. WHEN DATA BLOCK IS ALIGNED IN CORRECT POSITION OVER  
DRAWING FIDUCIALS ARE NOT CORRECTLY ORIENTED AND BASE SIDE OF  
FILM IS UP, CONTRARY TO DRAWING.

B. WHEN FIDUCIALS ARE ALIGNED TO DRAWING WITH FILM BASE DOWN,  
ROW OF REF LAMPS (THE ONLY LAMPS IMAGED IN DATA BLOCK ON SAMPLE)  
FALL IN VERY CLOSE PROXIMITY TO LEADING EDGE OF NEXT FRAME IN  
SEQUENCE. IF ALL LAMPS HAD BEEN ON, SOME LAMP IMAGES WOULD HAVE  
BEEN RECORDED INSIDE FRAME FORMAT ON NEXT FRAME.

2. TWO POSSIBLE EXPLANATIONS ARISE.

A. METERING PROBLEM EXISTED IN GROUND TEST.

B. IN RELOCATING DATA BLOCK HEAD IT HAS BEEN FLIPPED OVER  
SO THAT POSITION ON REF ROW IN RESPECT TO OTHER ROWS IS REVERSED  
FROM THAT SHOWN ON DRAWING.

3. REQUEST CLARIFICATION OF CORRECT POSITION AND ORIENTATION  
OF DATA BLOCK.

4. NEW SUBJECT: RECENT [ ] TRIP TO YOUR 25X1  
ACTIVITY MOST BENEFICIAL TO BOTH PARTIES. THANK YOU.

TOP SECRET

Declassification Review by NGA/DoD

25X1

25X1

25X1

25X1